

Residential Unitary R-410A Service Coils

| | | Current R-410A Coil Substitutions | | | |
|-------------|----------------------|-----------------------------------|-------------|-------------|-------------------|
| Coil Family | Current R-410A Coils | Sub-1 | Sub-2 | Sub-3 | New Service Coils |
| CAPE | CAPE4860C4 | | | | 0270D01062S |
| CAPE | CAPE4860D4 | | | | 0270D01063S |
| CAPE | CAPE4961C4 | | | | 0270D01064S |
| CAPE | CAPE4961D4 | | | | 0270D01065S |
| CAPE | CAPEA1818B4 | | | | 0270D01760S |
| CAPE | CAPEA2422B4 | | | | 0270D01763S |
| CAPE | CAPEA2422C4 | | | | 0270D01783S |
| CAPE | CAPEA3026B4 | | | | 0270D01764S |
| CAPE | CAPEA3026C4 | | | | 0270D01785S |
| CAPE | CAPEA3026D4 | | | | 0270D01786S |
| CAPE | CAPEA4830C4 | | | | 0270D01187S |
| CAPE | CAPEA6030D4 | | | | 0270D01188S |
| CAPF | CAPF3137B6 | CAUF3137B6 | | | 0270D00646S |
| CAPF | CAPF3743C6 | CAUF3743C6 | | | 0270D00611S |
| CAPF | CAPF4860D6 | CAUF4860D6 | | | 0270D00626S |
| CAPF | CAPFA1818A6 | CAUFA1818A6 | CAPFA2418A6 | CAUFA2418A6 | 0270D01811S |
| CAPF | CAPFA1818B6 | CAUFA1818B6 | CAPFA2418B6 | CAUFA2418B6 | 0270D01777S |
| CAPF | CAPFA1818C6 | CAUFA1818C6 | CAPFA2418C6 | CAUFA2418C6 | 0270D01812S |
| CAPF | CAPFA2318A6 | CAUFA2318A6 | CAPFA2418A6 | CAUFA2418A6 | 0270D01811S |
| CAPF | CAPFA2318B6 | CAUFA2318B6 | CAPFA2418B6 | CAUFA2418B6 | 0270D01777S |
| CAPF | CAPFA2318C6 | CAUFA2318C6 | CAPFA2418C6 | CAUFA2418C6 | 0270D01812S |
| CAPF | CAPFA2418A6 | CAUFA2418A6 | | | 0270D01811S |
| CAPF | CAPFA2418C6 | CAUFA2418C6 | | | 0270D01812S |
| CAPF | CAPFA2422A6 | CAUFA2422A6 | CAPFA3022A6 | CAUFA3022A6 | 0270D01815S |
| CAPF | CAPFA2422C6 | CAUFA2422C6 | CAPFA3022C6 | CAUFA3022C6 | 0270D01816S |
| CAPF | CAPFA2922A6 | CAUFA2922A6 | CAPFA3022A6 | CAUFA3022A6 | 0270D01815S |
| CAPF | CAPFA2922B6 | CAUFA2922B6 | CAPFA3022B6 | CAUFA3022B6 | 0270D01779S |
| CAPF | CAPFA2922C6 | CAUFA2922C6 | CAPFA3022C6 | CAUFA3022C6 | 0270D01816S |
| CAPF | CAPFA3022A6 | CAUFA3022A6 | | | 0270D01815S |
| CAPF | CAPFA3022C6 | CAUFA3022C6 | | | 0270D01816S |
| CAPF | CAPFA3022D6 | CAUFA3022D6 | | | 0270D01817S |
| CAPF | CAPFA3526B6 | CAUFA3526B6 | CAPFA4226B6 | CAUFA4226B6 | 0270D01791S |
| CAPF | CAPFA3526C6 | CAUFA3526C6 | CAPFA4226C6 | CAUFA4226C6 | 0270D01820S |
| CAPF | CAPFA3626C6 | CAUFA3626C6 | CAPFA4226C6 | CAUFA4226C6 | 0270D01820S |
| CAPT | CAPT3743C4 | CAUF3743C6 | | | 0270D00611S |
| CAPT | CAPT3743D4 | CAUF3743D6 | | | 0270D00612S |
| CAPT | CAPT4961C4 | CAUF4961C6 | | | 0270D00613S |
| CAPT | CAPT4961D4 | CAUF4961D6 | | | 0270D00614S |
| CAPT | CAPTA1818A4 | CAUFA1818A6 | | CAUFA2418A6 | 0270D01811S |
| CAPT | CAPTA2422A4 | CAUFA2422A6 | | CAUFA2418C6 | 0270D01812S |
| CAPT | CAPTA2422B4 | CAUFA2422B6 | | CAUFA3022B6 | 0270D01779S |
| CAPT | CAPTA3022A4 | CAUFA3022A6 | | | 0270D01815S |

Residential Unitary R-410A Service Coils

| Coil Family | Current R-410A Coils | Current R-410A Coil Substitutions | | | New Service Coils |
|-------------|----------------------|-----------------------------------|-------|-------------|-------------------|
| | | Sub-1 | Sub-2 | Sub-3 | |
| CAPT | CAPTA3022B4 | CAUFA3022B6 | | | 0270D01779S |
| CAPT | CAPTA3022C4 | CAUFA3022C6 | | | 0270D01816S |
| CAPT | CAPTA3026B4 | CAUFA3022D6 | | | 0270D01817S |
| CAPT | CAPTA3626C4 | CAUFA3626C6 | | CAUFA4226C6 | 0270D01820S |
| CAPT | CAPTA4230C4 | | | | 0270D01807S |
| CAUF | CAUFA1714A6 | | | | 0270D01724S |
| CAUF | CAUFA1714B6 | | | | 0270D01705S |
| CAUF | CAUFA1818C6 | CAUFA2418C6 | | | 0270D01812S |
| CAUF | CAUFA2318A6 | CAUFA2418A6 | | | 0270D01811S |
| CAUF | CAUFA2318B6 | CAUFA2418B6 | | | 0270D01777S |
| CAUF | CAUFA2318C6 | CAUFA2418C6 | | | 0270D01812S |
| CAUF | CAUFA2922A6 | CAUFA3022A6 | | | 0270D01815S |
| CAUF | CAUFA2922B6 | CAUFA3022B6 | | | 0270D01779S |
| CAUF | CAUFA2922C6 | CAUFA3022C6 | | | 0270D01816S |
| CAUF | CAUFA3022A6 | | | | 0270D01815S |
| CAUF | CAUFA3526B6 | CAUFA4226B6 | | | 0270D01791S |
| CHPE | CHPE2430B4 | | | | 0270D00926S |
| CHPE | CHPE3636B4 | | | | 0270D00927S |
| CHPE | CHPE3642C4 | | | | 0270D00928S |
| CHPE | CHPE3743C4 | | | | 0270D00929S |
| CHPE | CHPE3743D4 | | | | 0270D00930S |
| CHPE | CHPE4860D4 | | | | 0270D00987S |
| CHPF | CHPF1824A6 | | | | 0270D00615S |
| CHPF | CHPF2430B6 | CHPF3636B6 | | | 0270D00617S |
| CHPF | CHPF3636B6 | | | | 0270D00617S |
| CHPF | CHPF3642C6 | | | | 0270D00618S |
| CHPF | CHPF3743C6 | | | | 0270D00620S |
| CHPF | CHPF4860D6 | | | | 0270D00622S |
| CHPT | CHPT4860D4 | CHPF4860D6 | | | 0270D00622S |
| CHPT | CHPTA1822A4 | | | | 0270D01683S |
| CHPT | CHPTA3026C4 | | | | 0270D01688S |
| CHPT | CHPTA3630B4 | | | | 0270D01689S |
| CHPT | CHPTA3630C4 | | | | 0270D01690S |
| CSCF | CSCF1824N6 | | | | 0270D00395SLP |
| CSCF | CSCF3036N6 | | | | 0270D00396SLP |
| CSCF | CSCF3642N6 | | | | 0270D00397SLP |
| CSCF | CSCF4860N6 | | | | 0270D00398SLP |